



DAIMLERCHRYSLER



 General Motors

Date: May 28, 2008

Subject: Correction to USCAR 2 rev 5

To: Whom it may concern

A typographical error has been identified in SAE/USCAR 2 revision 5. Paragraph 5.4.7.3 Procedure should read:

16 sample pairs are required. (2 groups of 8) Samples are to be production intent. The connector cavities shall ~~be~~ not be populated with terminals.

Comments and or questions should be addresses to EWCAP@uscar.org

A handwritten signature in dark ink, appearing to read "Jim Roberts", with a long horizontal flourish extending to the right.

USCAR/EWCAP Jim Roberts

A handwritten signature in dark ink, appearing to read "Harry Zaverzence", with a large, stylized flourish at the bottom.

USCAR/EWCAP Harry Zaverzence